

**BOARD OF FIRE COMMISSIONERS
EAST BRUNSWICK FIRE DISTRICT NO. 1
MINUTES OF THE SPECIAL MEETING
February 3rd, 2026**

Commissioner Smith, Chairman, called the meeting to order at 7:00 PM in the meeting room of the Board of Fire Commissioners located at 310 Rues Lane, East Brunswick, NJ 08816.

Commissioner Smith led the Commissioners in the Pledge of Allegiance to the Flag and read the notice by R.S. 10-4, The Open Public Meetings Act, into the minutes. Notice of time, date, location and agenda of this meeting to the extent then known was duly published at least 48 hours in advance of this meeting by posting in the official newspaper of the Board and by posting on the official bulletin board of the Board of Fire Commissioners.

Roll Call:

Commissioner Ansalone:	Present
Commissioner Hoover:	Present (1) 3/18/2021
Commissioner McDonald:	
Commissioner Mosher:	Present
Commissioner Smith:	Present

Chief's Report: N/A

President's Report: N/A

Fire Marshal:

Fire Maintenance: see attached.

Building Maintenance Report: N/A

Legal: N/A

Treasurer's Report: See attached.

Motion to approve Treasurer's Report and authorize payment of properly audited bills.

Motion made by: Comm. Hoover Seconded by: Comm. Mosher

Roll call: Com. Hoover...aye/ Com. Ansalone...aye/ Com. Mosher...aye/ / Com. Smith...aye.
The motion was accepted and approved.

Approval of Minutes: N/A

Correspondence: N/A

Old Business: N/A

New Business:

Motion to authorize purchase of Tango Tango at Chief's request (Push to Talk System). This will pose no cost to the District.

Motion made by: Comm. Ansalone Seconded by: Comm. Smith

Roll call: Com. Hoover...aye/ Com. Ansalone...aye/ Com. Mosher...aye/ / Com. Smith...aye.
The motion was accepted and approved.


Adjournment:

Being no further discussion or business at this time, Commissioner Mosher made the motion seconded by Commissioner Mosher to adjourn the meeting at 7:30 pm.

Motion made by: Comm. Mosher Seconded by: Comm. Ansalone

Roll call: Com. Hoover...aye/ Com. Ansalone...aye/ Com. Mosher...absent/ / Com. Smith...aye. The motion was accepted and approved.

Respectfully submitted,

A handwritten signature in black ink, appearing to be 'F. Hoover', is written over a horizontal line. The signature is fluid and cursive.

Frederick Hoover, Clerk
Board of Fire Commissioners
East Brunswick Fire District No. 1

EAST BRUNSWICK FIRE DISTRICT #1
BOARD OF FIRE COMMISSIONERS

ROLL CALL TALLY SHEET

Meeting Date: 2-3-2026 Called to Order at: 7PM By: CHAIRMAN SMITH

Attendance: P - Present A - Absent

Ansalone P Hoover P McDonald — Mosher P Smith P

Motions Y - Yes N - No ABS - Absent ABST - Abstain

Motion to Approve TREASURERS Report & AOTA Payment of Property, Audited Bills

Motion made by: Hoover Seconded by: Mosher

Ansalone Y Hoover Y McDonald — Mosher Y Smith Y/S

Motion to AOTA Purchase of TANGO TANGO AT CHIEFS TRONTS (AOTA TO TALK SYSTEM) NO COST TO DISTRICT -

Motion made by: Ansalone Seconded by: Smith

Ansalone Y Hoover Y McDonald — Mosher Y Smith Y

Motion to Adourn @ 7:30pm

Motion made by: Mosher Seconded by: Ansalone

Ansalone Y Hoover Y McDonald — Mosher Y Smith Y

Motion made by: _____ Seconded by: _____

Ansalone _____ Hoover _____ McDonald _____ Mosher _____ Smith _____

2/3/24

Pledge of Allegiance

Chief's Report

New Business

Motion to adjourn 7:32

MM BS
FH SA

East Brunswick Fire District #1 Open Alerts as of February 3, 2026 10:47 AM for All Stations

ALERT ID	OPENED	OPENED BY	CATEGORY	UNIT / CHECKLIST	POSTED STATION	DESCRIPTION & COMMENTS	COST	PRIORITY	LAST UPDATE
1591090	02/01/2026 12:43 PM	Green, Joel	Equipment & Tools	704	Station 2	EQUIPMENT CHECK - Cascade System - Cascade Air Bank PSI Checks - Low air, will fill bank1 and bank 2 February 3, 2026 10:54 AM - Royce Cradic: Cascade system has a slow leak.		Routine	02/03/2026 10:54 AM
1588161	01/29/2026 10:34 AM	Cradic, Royce	Vehicle Maintenance	707	Station 2	Officers side mirror cannot be adjusted. Facing towards the ground and cannot be manually adjusted. This does not appear to be weather (frozen) related. February 3, 2026 10:54 AM - Royce Cradic: New mirror ordered by Fire and Safety		Urgent	02/03/2026 10:54 AM
1584383	01/25/2026 12:29 PM	Green, Joel	Marine Equipment	Marine 2 Trailer	Station 2	Trailer Check - Trailer Check - Brake and Tail Lights - Left tail light still not working		Routine	01/25/2026 12:29 PM
1584080	01/25/2026 08:49 AM	Cradic, Royce	Equipment & Tools	707	Station 2	Roof saw not starting January 25, 2026 08:50 AM - Royce Cradic: Saw will be dropped off at Pride for service.		Routine	01/25/2026 08:50 AM
1583757	01/24/2026 05:14 PM	Gahrmann, Justin	Equipment & Tools	708	Station 1	EQUIPMENT CHECK - Gas Detection Meters - RKI 4 Gas Secondary Meter Operation - Not on rig for inspection January 25, 2026 08:51 AM - Royce Cradic: New meter ordered January 26, 2026 08:33 AM - Royce Cradic: Invoice added	570.99	Routine	01/26/2026 08:33 AM
1577819	01/18/2026 12:47 AM	Green, Joel	Vehicle Maintenance	712	Station 2	Possibly related to the Whalen light control box February 3, 2026 10:56 AM - Royce Cradic: Fire and Safety will be notified for service		Routine	02/03/2026 10:56 AM
1575291	01/14/2026 06:16 PM	Jandemal, Matthew	Vehicle Maintenance	708	Station 1	CHASSIS CHECK - Pump Check - Intake Valves Operation - Front inlet turn valve extremely loose. Still operational. January 15, 2026 09:36 AM - Royce Cradic: Send to Fire and Safety		Routine	01/15/2026 09:36 AM
1572162	01/11/2026 01:29 PM	Green, Joel	Vehicle Maintenance	717	Station 2	VEHICLE CHECK - Chassis - Other Mechanical Issues - Right side cab not staying up. Bad hydraulic struts. January 14, 2026 08:29 AM - Royce Cradic: ARE SN: N3203447 STABILILUS LIFT-O-MAT HIGH PRESSURE January 14, 2026 08:34 AM - Royce Cradic: Photos added		Routine	01/14/2026 08:34 AM
1572161	01/11/2026 01:27 PM	Green, Joel	Vehicle Maintenance	717	Station 2	VEHICLE CHECK - Chassis - Body Damage - Peeling by back door		Routine	01/11/2026 01:27 PM
1565771	01/04/2026 12:15 PM	Green, Joel	Equipment & Tools	709	Station 2	EQUIPMENT CHECK - Miscellaneous Equipment - Search Rope - Not on T-709 January 5, 2026 12:02 PM - Royce Cradic: Search bags need to be replaced.		Routine	01/05/2026 12:02 PM
1554312	12/20/2025 03:28 PM	Green, Joel	Vehicle Maintenance	712	Station 2	VEHICLE CHECK - Chassis - Other Mechanical Issues - Missing right side back rubber gasket for roll top		Routine	12/20/2025 03:28 PM
1545832	12/09/2025 09:07 PM	Green, Joel	Equipment & Tools	709	Station 2	EQUIPMENT CHECK - Miscellaneous Equipment - Through the Floor Kit -		Routine	12/09/2025 09:07 PM

ALERT ID	OPENED	OPENED BY	CATEGORY	UNIT / CHECKLIST	POSTED STATION	DESCRIPTION & COMMENTS	COST	PRIORITY	LAST UPDATE
1499223	10/14/2025 07:39 PM	Mosher, Michael	Vehicle Maintenance	709	Station 2	CHASSIS CHECK - Pump Check - Discharge Valves Operation - 2.5" discharge not operational October 20, 2025 08:50 AM - Royce Cradic: Valve stuck closed - will not open Fire and Safety notified for repair		Routine	10/20/2025 08:50 AM
1497893	10/13/2025 10:34 AM	Cradic, Royce	Vehicle Maintenance	Brush 705	Station 2	Pump leaking. Service to be scheduled with Fire and Safety. October 20, 2025 08:51 AM - Royce Cradic: Fire and Safety notified for service		Routine	10/20/2025 08:51 AM
1482632	09/24/2025 03:00 PM	Cradic, Royce	Vehicle Maintenance	708R	Station 2	Front oscillating light in main light bar inoperable Fire and Safety PM Report		Routine	09/24/2025 03:00 PM
1482630	09/24/2025 02:59 PM	Cradic, Royce	Vehicle Maintenance	708R	Station 2	Hose clamp holding cooler hose is broken. Fire and Safety PM Report		Routine	09/24/2025 02:59 PM
1482629	09/24/2025 02:58 PM	Cradic, Royce	Vehicle Maintenance	708R	Station 2	Front discharge gauge in vacuum all the time. Fire and Safety PM Report		Routine	09/24/2025 02:58 PM
1482627	09/24/2025 02:56 PM	Cradic, Royce	Vehicle Maintenance	708R	Station 2	Passenger rear discharge gauge has no fluid in it. Fire and Safety PM Report		Routine	09/24/2025 02:56 PM
1482625	09/24/2025 02:55 PM	Cradic, Royce	Vehicle Maintenance	708R	Station 2	Number 1 discharge gauge cracked. Fire and Safety PM Report		Routine	09/24/2025 02:55 PM
1482624	09/24/2025 02:54 PM	Cradic, Royce	Vehicle Maintenance	708R	Station 2	Pinion seal wet. Fire and Safety PM Report		Routine	09/24/2025 02:54 PM
1481767	09/23/2025 01:26 PM	Cradic, Royce	Vehicle Maintenance	706	Station 3	Air dryer needs to be replace. Fire and Safety PM Report		Routine	09/23/2025 01:26 PM
1481766	09/23/2025 01:25 PM	Cradic, Royce	Vehicle Maintenance	706	Station 3	Passenger rear discharge gauge cracked Fire and Safety PM Report		Routine	09/23/2025 01:25 PM
1481762	09/23/2025 01:23 PM	Cradic, Royce	Vehicle Maintenance	706	Station 3	Officers seat belt torn. Fire and Safety PM Report		Routine	09/23/2025 01:23 PM
1481760	09/23/2025 01:22 PM	Cradic, Royce	Vehicle Maintenance	709	Station 2	Hydraulic leak on the passenger side hose that runs through the ladder. Fire and Safety PM Report		Routine	09/23/2025 01:22 PM
1481757	09/23/2025 01:21 PM	Cradic, Royce	Vehicle Maintenance	709	Station 2	Fuel tank leaking. Fire and Safety PM Report		Routine	09/23/2025 01:21 PM
1481752	09/23/2025 01:17 PM	Cradic, Royce	Vehicle Maintenance	702	Station 1	Transmission dipstick leaking where it goes into the transmission. Fire and Safety PM Report September 23, 2025 01:19 PM - Royce Cradic: PM Report added		Routine	09/23/2025 01:19 PM
1481725	09/23/2025 12:44 PM	Cradic, Royce	Vehicle Maintenance	702	Station 1	Insulation under cab falling off Fire and Safety PM Report		Routine	09/23/2025 12:44 PM
1481722	09/23/2025 12:43 PM	Cradic, Royce	Vehicle Maintenance	702	Station 1	Front shocks need replacement Fire and Safety PM Report		Routine	09/23/2025 12:43 PM
1481721	09/23/2025 12:43 PM	Cradic, Royce	Vehicle Maintenance	702	Station 1	Pump drain leaking under pressure. Fire and Safety PM Report		Routine	09/23/2025 12:43 PM
1481719	09/23/2025 12:42 PM	Cradic, Royce	Vehicle Maintenance	702	Station 1	AC vent broken. Fire and Safety PM Report		Routine	09/23/2025 12:42 PM
1481718	09/23/2025 12:42 PM	Cradic, Royce	Vehicle Maintenance	702	Station 1	Drivers side window difficult to crank closed. Fire and Safety PM Report		Routine	09/23/2025 12:42 PM
1481716	09/23/2025 12:39 PM	Cradic, Royce	Vehicle Maintenance	706	Station 3	Rear spotlight not working FireFlow Pump Test Report		Routine	09/23/2025 12:39 PM
1481715	09/23/2025 12:39 PM	Cradic, Royce	Vehicle Maintenance	706	Station 3	Drivers side 6" suction screen needs to be replaced. FireFlow Pump Test Report		Routine	09/23/2025 12:39 PM

ALERT ID	OPENED	OPENED BY	CATEGORY	UNIT / CHECKLIST	POSTED STATION	DESCRIPTION & COMMENTS	COST	PRIORITY	LAST UPDATE
1481714	09/23/2025 12:38 PM	Cradic, Royce	Vehicle Maintenance	709	Station 2	Drivers side 6" suction screen needs to be replaced. FireFlow Pump Test Report		Routine	09/23/2025 12:38 PM
1481712	09/23/2025 12:37 PM	Cradic, Royce	Vehicle Maintenance	708R	Station 2	LDH elbow needs a new gasket. FireFlow Pump Test Report		Routine	09/23/2025 12:37 PM
1481708	09/23/2025 12:35 PM	Cradic, Royce	Vehicle Maintenance	702	Station 1	Passenger side LDH (Green #2) linkage creeps closed under pressure. FireFlow Pump Test Report		Routine	09/23/2025 12:35 PM
1468952	09/07/2025 07:38 PM	Ranahan, Ryan	Vehicle Maintenance	706	Station 3	CHASSIS CHECK - Generator and Electrical - Light Tower - Stand is loose Stand is wobbly		Routine	09/07/2025 07:38 PM
1468950	09/07/2025 07:36 PM	Ranahan, Ryan	Vehicle Maintenance	706	Station 3	CHASSIS CHECK - Pump - Transfer Valve Operation - Volume light is out		Routine	09/07/2025 07:36 PM
1455850	08/23/2025 08:35 AM	Cradic, Royce	Vehicle Maintenance	708R	Station 2	Drivers side cab lift cylinder leaking. Fire and Safety will schedule repair.		Routine	08/23/2025 08:35 AM
1430840	07/25/2025 09:56 AM	Cradic, Royce	Vehicle Maintenance	708	Station 1	CHASSIS CHECK - Pump Check - Discharge Valves Operation - Closed light on Driver Rear Discharge A is not working August 18, 2025 09:35 AM - Royce Cradic: Fire and Safety notified and replacement ordered.		Routine	08/18/2025 09:35 AM
1416728	07/08/2025 07:49 AM	Cradic, Royce	Vehicle Maintenance	707	Station 2	Officers side brake light has LED's not working. August 5, 2025 08:50 AM - Royce Cradic: Part ordered. Will be replaced during Preventive Maintenance		Routine	08/05/2025 08:50 AM
1405959	06/25/2025 10:15 AM	Green, Joel	Equipment & Tools	709	Station 2	EQUIPMENT CHECK - Miscellaneous Equipment - Search Rope - Bag needs to be marked No draw string, missing out of bag. Bag not marked "Search Rope" and rope is friction burned or dirty.		Routine	06/25/2025 10:15 AM
1399028	06/09/2025 08:01 AM	Cradic, Royce	Vehicle Maintenance	709	Station 2	Front shocks need to be replaced. Other issues repaired and new separate Alert entered for the shocks. August 5, 2025 08:51 AM - Royce Cradic: Shocks will be replaced during Preventive Maintenance		Routine	08/05/2025 08:51 AM
1337924	04/01/2025 04:10 PM	Cradic, Royce	Vehicle Maintenance	Brush 703	Station 1	TRUCK CHECK - Chassis - Other Mechanical Issues - Fuel tank vent hose is leaking. Fire and Safety to be contacted for service.		Routine	04/01/2025 04:10 PM
1313739	03/03/2025 09:10 AM	Cradic, Royce	Vehicle Maintenance	715	Station 1	VEHICLE CHECK - Chassis - Other Mechanical Issues - Cap weather stripping damaged / cap third brake light has water in it Needs to be scheduled at Suburban Caps for repair December 2, 2025 08:14 AM - Royce Cradic: Needs to be repaired by the upfitter.		Routine	12/02/2025 08:14 AM